G-M Water Supply Corporation PO Box 727 Hemphill, TX 75948 409-787-2755

SEPTEMBER 22, 2023

TO WHOM IT MAY CONCERN,

G-M WATER SUPPLY CORP. CAN FURNISH POTABLE WATER TO THE PROPOSED SUBDIVISION DEVELOPMENT LOCATED NEAR PINEKNOT SUBDIVISION OFF SOUTHWOOD DRIVE PROVIDED THAT ONLY 9 METERS WILL BE INSTALLED. DUE TO THE CURRENT WATER MAIN SIZE AND CURRENT NUMBER OF ACTIVE METERS ALREADY IN THAT AREA OUR CAPACITY WILL NOT BE ABLE TO SUPPLY ANY MORE METERS THAN THAT WITHOUT AN UPGRADE TO THE DISTRIBUTION LINE.

THANK YOU,

JERRY PICKARD

G-M WATER SUPPLY CORP

"G-M Water Supply Corporation is an equal opportunity provider and employer"

SABINE RIVER AUTHORITY of Texas

Toledo Bend Division

450 Spur 135

Burkeville, Texas 75932

Phone: (409) 565–2273

Fax: (409) 565–2338

Randy Fuller

Subject - Subdivision Approval for Hamilton Landing at Mason Creek

Mr. Fuller,

The Sabine River Authority, Authorized Agent of the Texas Commission on Environmental Quality (TCEQ), recently received your overall onsite sewage facility (OSSF) planning materials and plat for your proposed subdivision "Hamilton Point Landing at Mason Creek" on Toledo Bend Reservoir. The OSSF planning materials have been reviewed according to the TCEQ's guidelines (TAC 285.4 (c)) and have been determined to meet that agency's minimum requirements which may allow the installation of certain onsite sewage facility systems.

The permit area boundaries on Sabine River Authority property and the subdivisions plat are determined to be satisfactory. Please have your surveyor pin the permit lines at the 172 elevation.

Please keep in mind this approval letter does not permit the installation of any OSSF. A site specific site evaluation and design is required on each individual lot prior to installation of any septic system.

Attached is an invoice for the subdivision review. The Authority appreciates your cooperation in this matter.

Thank you,

Ryan Pay

Toledo Bend Assistant Division Manager Sabine River Authority of Texas

Hamilton Landing

At

Mason Creek

Subdivision Restrictions

All parts, portions, parcels or lots of said tract shall be known and described as single-family residential lots. No lot shall be used for business purposes of any kind.

Only single-family residences with a minimum living area of 1,200 square feet shall be allowed to be constructed in said subdivision. No mobile homes or manufactured homes shall be allowed; nor shall any structure or building of any type be moved onto any lot.

Any structure constructed on said tracts or lots shall be completed on the outside within (9) months from the date of commencement of construction. Outside storage of building construction materials and building equipment shall be permitted only during (9) months construction period. All surfaces which normally require painting must be painted within sixty (60) days from the time of installation. All supporting buildings or outbuildings, storage houses, etc., shall be a commercial grade of exterior finish materials. No tar paper, imitation brick or like exterior material shall be permitted in the exterior construction of any building. No temporary structure such as a tent, shack, garage or other outbuilding shall be used on any lot as a residence except that temporary quarters in the form of a camper, motor home or travel trailer may be used during the construction of a permanent dwelling provided that such temporary structure is not permitted to remain on the property for more than (9) months.

No animals, livestock or poultry of any kind shall be raised, bred or kept on any lot except that dogs, cats and other household pets may be kept, provided that they are not kept, bred or maintained for any commercial purposes, except with the approval of the developers.

Vol 40 Page 791

No signs shall be erected in Hamilton Landing at Mason Creek unless specifically approved in writing by the developers, except for a "For Sale" sign which must be plain and neat, not larger than one (1) foot by two and one-half $(2\frac{1}{2})$ feet and except a homeowner name and address plate.

No lot in the subdivision may be sub-divided into smaller tracts or lots without the approval of the developers.

No residential structure shall be located nearer the front line than ten (10) feet, or nearer the side street line than ten (10) feet or nearer to the side lot line or rear lot line than five (5) feet.

No lot shall be used for the purpose of a dumping ground for trash, junked cars, or anything that is not in keeping with a well-planned subdivision.

If the owner of any lot in said subdivision or any other person shall violate any of the covenants herein, it shall be lawful for any other person or persons owning any real property situated in said subdivision to prosecute any proceedings at law or in equity against the person or persons violating or attempting to violate any such covenants and either to prevent him or them from doing so or to recover damages or other dues for such violation.

Invalidation of any one or more of these covenants and restrictions by judgment of any court shall in nowise affect any of the other covenants, restrictions and provisions herein contained and shall remain in full force and effect.

4283 SOUTHWOOD DRIVE LUFKIN, TX 75904 (936) 632-0585

April 10, 2024

Mr. Ryan Pay Toledo Bend Assistant Division Director Sabine River Authority 450 Spur 135 Burkeville, TX 75932

Re: Subdivision Development Plan-Hamilton Landing at Mason Creek Subdivision, Sabine County, TX.

Dear Mr. Pay:

This letter and attachments are being submitted on behalf of Hamilton Land, LLC and will serve as the "Development Plan" for the 50.489 acre tract identified herein. This property will be developed in two phases with Phase I being completed first.

The information presented in the attached documents is being submitted in accordance with TCEQ Title 30 TAC Chapter 285.4. facility planning rules.

If you have any questions or need further clarification, please do not hesitate to contact me at (936) 632-0585.

Sincerely,

David Arnold

D&S Environmental Services

Cc: Randy Fuller (Project Manager)

SUBDIVISION DEVELOPMENT PLAN SABINE COUNTY

Permitting Authority: Sabine River Authority of Texas

Pursuant to Texas Commission on Environmental Quality (TCEQ) On-Site Sewage Facility Regulations, Title 30 TAC Chapter 285.4; this subdivision development plan is being submitted for review and approval as outlined and described below:

Applicant / Developer: Hamilton Land LLC

No. 2 Research Place, Suite 310

Rockville, MD, 20850

Subdivision Name: Hamilton Landing at Mason Creek

Legal Description: (Attachment II, IIA)

52.489 acre tract of land (less 2 acres removed) or remaining portion being 50.489 acre tract in the James Mason Survey A-160 in Sabine County, Texas. The coordinates showing the general location of this property are: N31.49939, W-93.79031. Note: Attached survey documents are considered preliminary by the surveyor and are for general guidance for the tract of land until final sealed documents are provided.

Site Location: (Attachment I)

The identified 50.489 acre tract of land is located approximately 3.6 miles north of Milam, TX on State Highway 87, thence east 1.3 miles on Telephone Road to the intersection of Cedar Grove Road, thence right 1.4 miles to Southwood Drive, thence 1.5 miles just past Pineknot Lane, thence approximately 100 yards to the entrance of the subdivision property.

Project Purpose & Description: (Attachment II, IIA)

This 50.489 acre tract will be developed in two phases. Both phases are being subdivided for residential development. Phase I, as detailed in the attached survey, will be subdivided into 9 waterfront lots consisting of 15.851 acres. Phase II will consist of the remaining 34.638 acres. Phase II survey work will be completed as Phase I construction progresses. Phase II lots are interior lots and will be sized for compliance with Title 30 TAC Chapter 285.4(A). All Phase I lots are identified as being greater than ½ acre in size, with the smallest tract (lot 2) being 1.046 acres and the largest (lot 4) being 3.015

acres in size. Current planning is to develop Phase II interior lots into larger acreage tracts. Survey work will direct the developers decision on the exact tract layout.

All lots in Phase I will have access to and the ability to be connected to public water. Phase II will have access to public water after a new line is installed by GM Water Supply Corp. This 50.489 acre tract is located outside of an incorporated city limits, so there is no organized sewer collection facility available for this subdivision. The installation of an on-site sewer facility (OSSF) is the most economical method of sewage disposal for each of the dedicated lots in this subdivided property.

Site Description Phase I: (Attachment IIA, IIB)

This 15.851 acre tract sits on the shoreline of Toledo Bend Reservoir in the Mason Creek area. The nine lots have waterfront access, some to open water and others to coves. The 15.851 acre tract has been cleared of most all underbrush and the timber thinned. There are sporadic mature oaks and pine left on most all lots. The topography of this site consists of varying elevation changes, with the lowest being approximately 175 ft. MSL (mean sea level) elevation and the highest being approximately 250 ft. MSL elevation. The contours for the most part are considered gentle to moderate rolling and some fairly sharp sloping contours located on the eastern boundary lines of identified lots adjacent to the SRA lease back line of Toledo Bend Reservoir. Some of the eastern facing lots have experienced extensive erosion over the years creating bluff bank conditions.

Site Description Phase II: (Attachment II, IIB)

The remainder 34.638 acre tract sits adjacent to the Phase I lots and will be considered interior lots, as no portion of this property touches the SRA leaseback areas. This portion of the property has not been cleared and has a large percentage of old growth pine and mixed hardwood. The topography of this site consists of varying elevation changes; the contours for the most part are considered gentle to moderate rolling with some fairly sharp sloping contours directing surface drainage towards the lake. A portion of this tract will include access roads, streets and utility easements as deemed necessary by the site survey work. Most all proposed lots will be comprised of multiple acreage.

Water Supply:

A portion of the 50.489 acre tract will be serviced by GM Water Supply Corporation. Phase I lots will be connected to a supply line provided by the developer to the GM main supply line. Additional water lines will need to be installed/replaced to insure adequate volume to Phase II homes. There are no known private water wells or abandoned water wells located on this 50.489 acre tract. There are no known subdivision restrictions that would prevent a future lot owner from pursuing the installation of a private well. Any

Vol 4-C Page 79

4/11/2024

private well being considered shall adhere to TCEQ water well setback requirements and to the Texas Water Well Driller Board regulations. A minimum of one acre will be required for consideration of a private well. It should be noted that any water wells placed onto an individual lot could possibly affect the development of adjacent lots due to setback requirements. The sewer and well placement locations should be considered at the planning stages for any lot development to minimize the possibility of limiting the development of adjacent lots.

Soil Survey & Site Evaluation: (Attachment III)

Based on USDA Natural Resources Conservation Service soil survey map, this 50.489 acre tract is composed primarily of (EasE) Eastwood very fine sandy loam w/5-20% slopes, (MhC) Hallsummit fine sandy loam w/1-5% slopes, and (SfA) Sawtown very fine sandy loam, 0-2% slopes. With the present land clearing and grading for Phase I sites, some, if not all surface soils, have been displaced or disturbed and may not be as described in the USDA classification.

Site Evaluation: (Attachment IV, a-i)

In compliance with TCEQ Subchapter D, 285.30, a site evaluation was performed on the morning of 3/14/2024, to evaluate general soil and groundwater conditions which would be applicable for OSSF installations on the 15.851acre tract (Phase I). A soil sample was taken from each of the nine lots to insure a representative soil evaluation could be accomplished for the tract. The nine locations were bored with a 3" hand auger to an average depth of 8". The samples were extruded and examined in the field to determine soil classification and the potential presence of groundwater. The samples indicated an average depth of sandy loam (class II) to 5", silty clay (class III) to 9", and a (class IV) from 10"+. This limited field investigation revealed that soil texture is relatively consistent throughout, showing that a class IV soil (high clay content) is relatively shallow throughout the site. Lot 7 had the highest concentration of sandy loam soil which reached a depth of 8". The high clay content of the soil eliminates the possibility of a conventional sewer system with subsurface disposal on any of the designated lots.

It should be noted that no groundwater was encountered to the depths between 2" and 16" at the sample sites. A fairly tight red to red-gold clay was present at all the bore sites. Some horizontal groundwater flow may be occurring at deeper depths on portions of the 50.489 acre site, but that evaluation is not within the project scope.

Drainage/Flood Zone Assessment:

Research indicates that there are no FEMA Flood Hazard maps published for Sabine County. Portions of each of the nine lots in Phase I will reach and abut the 175' elevation mark which indicates the leaseback line for SRA. This line will be shown on the final site survey submitted by the contracted registered professional land surveyor to the property owner and to SRA.

Topographic Site Data: (Attachment V)

Topographic maps of the area, as well as a recent property survey were reviewed and evaluated with respect to the potential effects of flooding. The subdivision development areas range from 175.0 ft.MSL to 250.0 ft. MSL. As per SRA requirements, all habitable structures and sewer components shall be located at or above 175.0 ft. MSL. The Toledo Bend Reservoir full pool elevation is at 172.0 ft. MSL. Based on site contours and elevations, surface runoff will be directed to different points on the 50.489 acre tract and at no point should there be concerns of direct flooding which would compromise the sewer components from elevated pool levels or low lying flooding. As lots are developed, consideration shall be given to home design to minimize the sewer components being contained in areas which could take on surface runoff and affect the operation of the aerobic treatment units (ATU).


OSSF Recommendations for Proposed Development:


Based on a site assessment conducted on March 14, 2024 and available information, the soils in the identified areas of this subdivision are not conducive for subsurface sewer disposal (conventional treatment). The aerobic treatment units (ATU's) with surface application will be the minimum required treatment method for this residential development. Individual lots may require ATU's with drip disposal based on contours and lot development limiting factors.


Each lot will require an individual site evaluation and OSSF design for compliance with applicable TCEQ and SRA regulations. This process should be included in the planning stages of each lot development.

Compliance with TCEQ Chapter 285.91(Table 10) separation distances is required for these subdivided lots.

Any proposed OSSF shall comply with all applicable rules as outlined in Title 30 TAC Chapter 285-32, 33 &34.








Attachment

Vol <u>4-C</u> Page <u>800</u>



Contact Us Subscribe M Archived Soil Surveys Soil Survey Status Glossary Preferences Link Logout Help

Attachment III

Area of Interest (AOI)

Soil Map

Soil Data Explorer

Download Soils Data

Shopping Cart (Free)


Search ← ← Clear Search **Basic Search** Enter keywords **Advanced Search** ← → Clear Search

Map Unit Legend

San Augustine and Sabine Counties, Texas (TX619)

San Augustine and Sabine Counties, Texas (TX619)

Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI
EasE	Eastwood very fine sandy loam, 5 to 20 percent slopes	33.5	36.6%
MhC	Hallsummit fine sandy loam, 1 to 5 percent slopes	39.4	43.0%
SfA	Sawtown very fine sandy loam, 0 to 2 percent slopes	1.8	1.9%
W	Water	16.9	18.5%
Totals for Area of Interest		91.6	100.0%




Warning: Soil Map may not be valid at this scale,

You have zoomed in beyond the scale at which the soil map for this area is intended to be used. Mapping of soils is done at a particular scale. The soil surve mapped at 1:24,000. The design of map units and the level of detail shown in the resulting soil map are dependent on that map scale.

DATE: 4/3/224 HOMEBUSINESS OWNER HAMILTON LAND LLC PR SUBDIVISION: HAMILTON LAND LLC PR SURVEY: JAMES MASON AT MASON CRESECTION SURVEY: JAMES MASON ABSTR STREET ADDRESS TBD. MILLIAM IX ACREAGE/LOT SIZE 50.489 TOTAL, PIMSE	1-2029@ 10:30m 1156:T TOT 1-9 ACT 160	Number 82824 Attachment IV BLOCK HCRES (FMOR-OF)OTHER
FLO	OD PLAIN	
		property this need Thinks r
		REMANUAL HAS NOT BEEN
-	eleanor - old 6	οροιστΑ.
	.,	MUPEUT IS ADJRECUT TO SRA
IN 100 YEAR FLOOD PLAIN AND FLOODWAY	LEASE BACK LINE	@ 175'ELEW
WATI	CR SUPPLY	
PUBLIC COMMUNITY	PRIVATE	
SIZE OF WELL YEAR DRILLED DRILL DEPTH OF WELL FEET	ER:	
ALL WELL REQUIRED DISTANCES MUST BE MAINTAINED		
IF NEIGHBORING WELLS EXIST THEY MUST BE SHOWN ON TO	HE DESIGN	
WASTEWAT	ER USAGE RATE	
TYPE OF FACILITY KESING TIME SUBDIVISION USAGE RA	2000	
on of the barrier of		
SEE INDIVIDUAL BORE	ANALYSIS 0_	
TE NOW DORE	SHEETS - ATTACHT	do
X SOIL TEXTURE	SOIL CLASS	LONG TERM LOADING RATE
	CONTRACTOR OF THE PROPERTY OF	
X SOIL TEXTURE	SOIL CLASS	LONG TERM LOADING RATE
X SOIL TEXTURE COURSE SAND/GRAVEL	SOIL CLASS	LONG TERM LOADING RATE >.50
X SOIL TEXTURE COURSE SAND/GRAVEL SAND/LOAM SAND	SOIL CLASS Ia Ib	>.50 0.38
X SOIL TEXTURE COURSE SAND/GRAVEL SAND/LOAM SAND SANDY/LOAM/LOAM SANDY CLAY LOAM/SANDY CLAY/CLAY LOAM/SILTY CLAY LOAM/	SOIL CLASS Ia Ib II	2.50 0.38 0.25
X COURSE SAND/GRAVEL SAND/LOAM SAND SANDY/LOAM/LOAM SANDY CLAY LOAM/SANDY CLAY/CLAY LOAM/SILTY CLAY LOAM/ SILTY LOAM/SILTY CLAY/SILTY CLAY	SOIL CLASS Ia Ib II III	2.50 0.38 0.25 0.20 0.10
X SOIL TEXTURE COURSE SAND/GRAVEL SAND/LOAM SAND SANDY/LOAM/LOAM SANDY CLAY LOAM/SANDY CLAY/CLAY LOAM/SILTY CLAY LOAM/ SILTY LOAM/SILT CLAY/SILTY CLAY INDICATION OF SEASONAL WATER TABLE	SOIL CLASS Ia Ib II III IV YES NO	LONG TERM LOADING RATE >.50
SOIL TEXTURE COURSE SAND/GRAVEL SAND/LOAM SAND SANDY/LOAM/LOAM SANDY CLAY LOAM/SANDY CLAY LOAM/SILTY CLAY LOAM/ SILTY LOAM/SILTY CLAY/SILTY CLAY INDICATION OF SEASONAL WATER TABLE NO MOISTURE PROSENT TO MITH BORE DEAT OF	SOIL CLASS Ia Ib II III IV YES L6 47	LONG TERM LOADING RATE >.50
SOIL TEXTURE COURSE SAND/GRAVEL SAND/LOAM SAND SANDY/LOAM/LOAM SANDY CLAY LOAM/SANDY CLAY LOAM/SILTY CLAY LOAM/ SILTY LOAM/SILTY CLAY/SILTY CLAY INDICATION OF SEASONAL WATER TABLE NO MOISTURE PROSENT TO MITH BORE DEAT OF	SOIL CLASS Ia Ib II III IV YES L6 47	LONG TERM LOADING RATE >.50
SOIL TEXTURE COURSE SAND/GRAVEL SAND/LOAM SAND SANDY/LOAM/LOAM SANDY CLAY LOAM/SANDY CLAY/CLAY LOAM/SANDY CLAY LOAM/ SILTY LOAM/SILTY CLAY CLAY/SILTY CLAY INDICATION OF SEASONAL WATER TABLE NO MOISTURE PRESANT TO MAX BORE DEAT OF NOTE: Subsurface horizons with colors of red, yellow and brown generally it that are in colors of gray, olive or blackish colors indicate poor aeration and s tables within 36 inches of the surface or has ground water visible in the test be conventional subsurface disposal due to internal drainage.	Ia Ib II III IV YES No dicate good soil aeration a bil drainage. Any soil profere less than 48 inches below	LONG TERM LOADING RATE >.50
SOIL TEXTURE COURSE SAND/GRAVEL SAND/LOAM SAND SANDY/LOAM/LOAM SANDY CLAY LOAM/SANDY CLAY LOAM/SILTY CLAY LOAM/ SILTY LOAM/SILTY CLAY/SILTY CLAY INDICATION OF SEASONAL WATER TABLE NO MOISTURE PROGRAT TO MITE BORE DEAT OF NOTE: Subsurface horizons with colors of red, yellow and brown generally in that are in colors of gray, olive or blackish colors indicate poor aeration and stables within 36 inches of the surface or has ground water visible in the test be conventional subsurface disposal due to internal drainage. Due to % Clay Course Acrosic Treatment Reco	Ia Ib II III IV YES No dicate good soil aeration a bil drainage. Any soil profere less than 48 inches below	LONG TERM LOADING RATE >.50
SOIL TEXTURE COURSE SAND/GRAVEL SAND/LOAM SAND SANDY/LOAM/LOAM SANDY CLAY LOAM/SANDY CLAY/CLAY LOAM/SILTY CLAY LOAM/SILTY CLAY LOAM/SILTY CLAY CLAY/SILTY CLAY INDICATION OF SEASONAL WATER TABLE NO MOISTURE PROGRAT TO MITH BORE DEAT OF NOTE: Subsurface horizons with colors of red, yellow and brown generally in that are in colors of gray, olive or blackish colors indicate poor aeration and stables within 36 inches of the surface or has ground water visible in the test be conventional subsurface disposal due to internal drainage. Due to % Clay Course Acrosic Transmer Reco	Ia Ib II III IV YES No dicate good soil aeration a soil drainage. Any soil profree less than 48 inches below	LONG TERM LOADING RATE >.50 0.38 0.25 0.20 0.10 DEPTH Ind drainage throughout the year. Subsurface horizons lile that has the grayish colors indicative of high water with the ground surface shall be deemed unsuitable for
SOIL TEXTURE COURSE SAND/GRAVEL SAND/LOAM SAND SANDY/LOAM/LOAM SANDY CLAY LOAM/SANDY CLAY/CLAY LOAM/SILTY CLAY LOAM/ SILTY LOAM/SILTY CLAY INDICATION OF SEASONAL WATER TABLE NO MOISTURE PRESON TO MITE BORE DETTOR NOTE: Subsurface horizons with colors of red, yellow and brown generally it that are in colors of gray, olive or blackish colors indicate poor aeration and stables within 36 inches of the surface or has ground water visible in the test be conventional subsurface disposal due to internal drainage. DETO SOLAM CONTENT ACCOUNT TOWNSTEM? L David Amold a Registered Sanitarian and Licensed Site Evaluator, did personally	Ia Ib II III IV YES Adicate good soil aeration a bild drainage. Any soil profire less than 48 inches below YES YES YES YES YES YES YES YES	LONG TERM LOADING RATE >.50 0.38 0.25 0.20 0.10 DEPTH Ind drainage throughout the year. Subsurface horizons lile that has the grayish colors indicative of high water with the ground surface shall be deemed unsuitable for
SOIL TEXTURE COURSE SAND/GRAVEL SAND/LOAM SAND SANDY/LOAM/LOAM SANDY/LOAM/LOAM SANDY CLAY LOAM/SANDY CLAY/CLAY LOAM/SILTY CLAY LOAM/ SILTY LOAM/SILTY CLAY INDICATION OF SEASONAL WATER TABLE NO MOISTURE PRESENT TO MITE BORE DETERMINED NOTE: Subsurface horizons with colors of red, yellow and brown generally in that are in colors of gray, olive or blackish colors indicate poor aeration and stables within 36 inches of the surface or has ground water visible in the test be conventional subsurface disposal due to internal drainage. DETO SOLUM CONTENT ACCOUNT TOWNSTEM? I, David Arnold, a Registered Sanitarian and Licensed Site Evaluator, did personally Sames MIASON SOLUM A DOMESTIES	Ia Ib II III IV YES No dicate good soil aeration a bil drainage. Any soil profore less than 48 inches below YES	LONG TERM LOADING RATE >.50 0.38 0.25 0.20 0.10 DEPTH Ind drainage throughout the year. Subsurface horizons lile that has the grayish colors indicative of high water with the ground surface shall be deemed unsuitable for
SOIL TEXTURE COURSE SAND/GRAVEL SAND/LOAM SAND SANDY/LOAM/LOAM SANDY CLAY LOAM/SANDY CLAY/CLAY LOAM/SILTY CLAY LOAM/ SILTY LOAM/SILTY CLAY INDICATION OF SEASONAL WATER TABLE NO MOISTURE PRESON TO MITE BORE DETTOR NOTE: Subsurface horizons with colors of red, yellow and brown generally it that are in colors of gray, olive or blackish colors indicate poor aeration and stables within 36 inches of the surface or has ground water visible in the test be conventional subsurface disposal due to internal drainage. DETO SOLAM CONTENT ACCOUNT TOWNSTEM? L David Amold a Registered Sanitarian and Licensed Site Evaluator, did personally	Ia Ib II III IV YES Adicate good soil aeration a bild drainage. Any soil profire less than 48 inches below YES YES YES YES YES YES YES YES	LONG TERM LOADING RATE >.50 0.38 0.25 0.20 0.10 DEPTH Ind drainage throughout the year. Subsurface horizons lile that has the grayish colors indicative of high water with the ground surface shall be deemed unsuitable for
SOIL TEXTURE COURSE SAND/GRAVEL SAND/LOAM SAND SANDY/LOAM/LOAM SANDY/LOAM/LOAM SANDY CLAY LOAM/SANDY CLAY/CLAY LOAM/SILTY CLAY LOAM/ SILTY LOAM/SILTY CLAY INDICATION OF SEASONAL WATER TABLE NO MOISTURE PRESENT TO MITE BORE DETERMINED NOTE: Subsurface horizons with colors of red, yellow and brown generally in that are in colors of gray, olive or blackish colors indicate poor aeration and stables within 36 inches of the surface or has ground water visible in the test be conventional subsurface disposal due to internal drainage. DETO SOLUM CONTENT ACCOUNT TOWNSTEM? I, David Arnold, a Registered Sanitarian and Licensed Site Evaluator, did personally Sames MIASON SOLUM A DOMESTIES	Ia Ib II III IV YES Adicate good soil aeration a bild drainage. Any soil profire less than 48 inches below YES YES YES YES YES YES YES YES	LONG TERM LOADING RATE >.50 0.38 0.25 0.20 0.10 DEPTH

Vol 4-C Page 803

SITEEVAL




Sent from my iPhone

N 31,49896° W -93,79327°

B1 0"-2" CLASS II
2"-4" CLASS III
4"+ CLASS IX

BROWN TO RED SLICK CLAY




N 31.49956° W -93,79357°


Bi O"-2" CLASS II SANDY LOAM

2"+ CLASS IV RED-BROWN CLAY

EASILY



N 31,49954° W -93,79268°



BI

N 31.49981°


W -93, 79 206°

0"-4" I

4"- 7" III

7"+ IV REO-GOLD-BROWN CLAY TIGHT - BALLS EASILY

Attachment II e



N 31.50063° W -93,79112°

BI O"-7" SANDY LOAM CLASS II


7"-16" SANDY CLAY CLASS III

16"+ GOLD RED SLICK

STICKY CLAY CLASS IV

VOI 4-C Page 308

Attachment II f



N. 31. 50030° W -93.79090°


BI O"-7" CLASS II SANDY COAM

7"- 12" SANDY CLAY, GOLD LT. BROWN

W/ MOISTURE - SLICK.

12" + W CLAY - SLICK + FEATHERS EASILY.

Vol 4-C Page 3.09



N 31,50002°

W -93,79052°

B, O"- 8" CLASS IT

8"-10" CLASS III SAUDY GOLD CLAY

10"+ CLASS II RED-GOW-CLAY



N 31,49939° W 793,79031°

0"-6" CLASS II W/ SOME GRAVEL

6"-9" CLASS III SANDY CLAY


9"+ CLASS IV RED/GOLD CLAY

Bore sites-Hamilton Landing

David Arnold <d.s.environmental@hotmail.com>

Fri 3/22/2024 2:31 PM

To:David Arnold <d.s.environmental@hotmail.com>



Attachment II i

N 31. 49862

W-93.79064

B1 0"-3" CLASS III
3"-5" CLASS III
5"+ CLASS IV

Vol 4-C page 8/2

SABINE RIVER AUTHORITY of Texas

Toledo Bend Division

450 Spur 135
Burkeville, Texas 75932
Phone: (409) 565–2273
Fax: (409) 565–2338

Randy Fuller

Subject - Subdivision Approval for Hamilton Landing at Mason Creek

Mr. Fuller,

The Sabine River Authority, Authorized Agent of the Texas Commission on Environmental Quality (TCEQ), recently received your overall onsite sewage facility (OSSF) planning materials and plat for your proposed subdivision "Hamilton Landing at Mason Creek" on Toledo Bend Reservoir. The OSSF planning materials have been reviewed according to the TCEQ's guidelines (TAC 285.4 (c)) and have been determined to meet that agency's minimum requirements which may allow the installation of certain onsite sewage facility systems.

The permit area boundaries on Sabine River Authority property and the subdivisions plat are determined to be satisfactory. Please have your surveyor pin the permit lines at the 172 elevation.

Please keep in mind this approval letter does not permit the installation of any OSSF. A site specific site evaluation and design is required on each individual lot prior to installation of any septic system.

Attached is an invoice for the subdivision review. The Authority appreciates your cooperation in this matter.

Ryan Pay

Thank you,

Toledo Bend Assistant Division Manager Sabine River Authority of Texas

Deep East Texas Electric Cooperative, Inc.





Local: (936) 229-4000 Toll Free: 1-866-392-2547 For Outages: 1-800-392-5986 Fax: (936) 275-2135

October 1, 2024

Hamilton Lands LLC 2 Research Place 310 Site # Rockville, MD 20850

Mr. Randy Fuller

As of May for 2024 the job was completed to install primary lines and poles for 9 lots at the Hamilton Lands subdivision. I've added a screenshot where it shows the job was completed on May 7th, 2024.

tion: Specific Job Nu	ımber •	Search	Add Add from S	00	Th Notes					
otes b			View Add		Job				Control control to the first state of the board of the board of	
JOHNK THU.	MAY 09, 2024, 02:04 PM				Date	Time	Туре			
ECHO COMPLETED 3	IOB ON 5-7-24		1		Thu 5/9/2024 ECHO COMPLET Wed 5/1/2024 GAVE NO# 346	the same to be a second to	9:27 AM	I	JOHNK	
Job Dates Statisti	cal Information Estimate	s Staking		1	Wed 5/1/2024 REC'D LOCATE RELEASE TO S		8:18 AM	I	PAMELAA	-
Job Number	34669	- - I - I - I - I - I - I - I - I - I	State	1-TX -	Tue 4/30/2024	16 258 31	12:43 PM	I	VANESSAS	-
Job Name Telephone	HAMILTON LANDS LLC 206-669-3400		County City:	[6 [B]	REC'D EASE- REC'D IA - T	THOMAS HAM HOMAS HAM	LMILTON ILTON			
relephone	1200-003-3400		Tax District	l WJ	Tue 4/9/2024		11:03 AM	I	VANESSAS	
Estimate Job Only: Work Order Type: Work Plan Nbr. Application Date Desired Date: District: Warehouse	No OYes	Year 24	Type Construction Cd Member Nbr. Service Order Project	Overhead Oundergroun Outlity 270814 S02355	PRIMARY LINE POLE NO. MILAM -87N R	S AND POLI	11:03 AM ES TO NEW SU ELEPHONE RD 4 TO LOC ON	I B DIVISION 1.2M RIGHT O	VANESSAS N CEDAR GROVE 1.2M TO AMILTON LANDS S/D	
Description	0									

Vanessa Santana Engineering Secretary 936-229-4000